
Inspector: Nick Cisney
Facility: SoloPower Systems

Inspection Date/Time:1/22/2019 @ 12:55 PM

PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES



The next several photos are from an inspection of the SoloPower facility on 9/26/2018. These photos document some of the unused chemicals, non-hazardous and hazardous wastes, and wastewater abandoned at the facility. At this time, Tetra Tech had been hired to document all wastes and hire a contractor to dispose of it properly.

Photos of the final inspection on 1/22/2019 are in the second half of this log.

9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.



9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.



Totes of chemicals and wastewater abandoned at the facility.



Inspector: Nick Cisney
Facility: SoloPower Systems

Inspection Date/Time:1/22/2019 @ 12:55 PM

PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES




9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.




9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.



9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.



9/26/2018:


Totes of chemicals and wastewater abandoned at the facility.

Inspector: Nick Cisney
Facility: SoloPower Systems

Inspection Date/Time:1/22/2019 @ 12:55 PM


PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES




9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.




9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.



9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.



9/26/2018:

Totes of chemicals and wastewater abandoned at the facility.

Inspector: Nick Cisney
Facility: SoloPower Systems

Inspection Date/Time:1/22/2019 @ 12:55 PM


PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES



1/22/2019:

Gated area on main production floor, SE corner of building, had chemicals stored here which have been removed.




1/22/2019:

Gated area on main production floor, SE corner of building, had chemicals stored here which have been removed.



1/22/2019:

Plating room, all chemicals removed. Hoses and pipes on plating machine have been drained.



1/22/2019:

All chemical totes and wastewater in the pretreatment room has been removed.

Inspector: Nick Cisney
Facility: SoloPower Systems

Inspection Date/Time:1/22/2019 @ 12:55 PM


PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES




1/22/2019:

All chemical totes and wastewater in the pretreatment room has been removed. Totes and drum in background are empty, caution tape used to segregate Clean Harbors equipment and supplies until they return to pick them up.




1/22/2019:

All chemical totes and wastewater in the pretreatment room has been removed.



1/22/2019:

All chemical totes and wastewater in the pretreatment room has been removed.



1/22/2019:


Process wastewater discharge point, covered.

Inspector: Nick Cisney
Facility: SoloPower Systems


Inspection Date/Time:1/22/2019 @ 12:55 PM

PHOTOS


CAPTIONS/PHOTO LOCATION SCREEN CAPTURES



1/22/2019: Process wastewater discharge point, dry.



1/22/2019: Plating room, totes of chemicals removed.



1/22/2019: VOC room, all chemicals removed, flammable cabinet empty



1/22/2019: All flammable cabinets are emptied out.

Inspector: Nick Cisney Inspection Date/Time:1/22/2019 @ 12:55 PM Facility: SoloPower Systems

PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES



1/22/2019:

Looking down the south wall of the main production floor. Carbon air filters in foreground to be removed.

Inspector: Nick Cisney	Inspection Date/Time:1/22/2019 @ 12:55 PM
Facility: SoloPower Systems	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES